

Stationsmerkmale und Bewertungen des Erscheinungsbildes

Stadt / Kreis Station	VRR Bewertungen des Erscheinungsbildes									behinderter- gerechter Zugang zum Bahnsteig	Förderprogr- amme, Ausbaumaß- nahmen
	Gesamtbewertung 2012	Gesamtbewertung 2013	Gesamtbewertung 2014	Bewertung 2014							
				Zugang			Bahnsteig				
				Sauberkeit	Funktion	Graffiti	Sauberkeit	Funktion	Graffiti		
Kreis Mettmann											
Erkrath *	●	●	●	●	●	●	●	●	●	A	
Erkrath Nord	●	●	●	●	●	●	●	●	●	R	
Hochdahl *	●	●	●	●	●	●	●	●	●		Modernisierung in der Umsetzung bzw. Planung im Rahmen MOF 2
Hochdahl-Millrath *	●	●	●	●	●	●	●	●	●	A	
Haan	●	●	●	●	●	●	●	●	●		Modernisierung erforderlich, Finanzierung nicht gesichert
Gruiten	●	●	●	●	●	●	●	●	●		Modernisierung erforderlich, Finanzierung nicht gesichert
Hilden *	●	●	●	●	●	●	●	●	●	A	
Hilden Süd *	●	●	●	●	●	●	●	●	●	A	
Langenfeld (Rheinl.)	●	●	●	●	●	●	●	●	●	A/R	
Langenfeld-Berghausen	●	●	●	●	●	●	●	●	●		
Mettmann Zentrum	●	●	●	●	●	●	●	●	●	A	
Mettmann Stadtwald	●	●	●	●	●	●	●	●	●	R	
Neanderthal	●	●	●	●	●	●	●	●	●	R	
Ratingen Ost *	●	●	●	●	●	●	●	●	●	A	Modernisierung im Rahmen MOF 2 erfolgt
Hösel *	●	●	●	●	●	●	●	●	●	R	Modernisierung in der Umsetzung bzw. Planung im Rahmen MOF 2
Velbert-Langenberg	●	●	●	●	●	●	●	●	●	A	
Velbert-Neuves	●	●	●	●	●	●	●	●	●	A	
Velbert-Nierenhof	●	●	●	X	X	X	●	●	●	R	
Velbert-Rosenhügel	●	●	●	●	●	●	●	●	●	R	
Wülfrath-Aprath	●	●	●	●	●	●	●	●	●	A	